



Imperial Conversion Chart

Please note that all the dimensions in this catalogue are in millimetres (mm) unless otherwise stated. To convert your imperial sizes to millimetres please use the conversion chart below.

Fractional	Decimal	mm
1/64	0.02	0.40
1/32	0.03	0.79
3/64	0.05	1.19
1/16	0.06	1.59
5/64	0.08	1.98
3/32	0.09	2.38
7/64	0.11	2.78
1/8	0.13	3.17
9/64	0.14	3.57
5/32	0.16	3.97
11/64	0.17	4.36
3/16	0.18	4.76
13/64	0.20	5.16
7/32	0.22	5.56
15/64	0.23	5.95
1/4	0.25	6.35
17/64	0.27	6.75
9/32	0.28	7.14
19/64	0.30	7.54
5/16	0.31	7.94
21/64	0.33	8.33
11/32	0.34	8.73
23/64	0.35	9.13
3/8	0.38	9.52
25/64	0.39	9.92
13/32	0.41	10.32
27/64	0.42	10.72
7/16	0.44	11.11
29/64	0.45	11.51
15/32	0.47	11.91
31/64	0.48	12.30
1/2	0.50	12.70

Fractional	Decimal	mm
33/64	0.52	13.10
17/32	0.53	13.49
35/64	0.55	13.89
9/16	0.56	14.29
37/64	0.58	16.68
19/32	0.59	15.08
39/64	0.61	15.48
5/8	0.63	15.88
41/64	0.64	16.27
21/32	0.66	16.67
43/64	0.67	17.07
11/16	0.69	17.46
45/64	0.70	17.85
23/32	0.72	18.26
47/64	0.73	18.65
3/4	0.75	19.05
49/64	0.77	19.45
25/32	0.78	19.84
51/64	0.80	20.24
13/16	0.81	20.63
53/64	0.83	21.03
27/32	0.84	21.43
55/64	0.86	21.83
7/8	0.87	22.23
57/64	0.89	22.62
29/32	0.91	23.02
59/64	0.92	23.42
15/16	0.94	23.81
61/64	0.95	24.21
31/32	0.97	24.61
63/64	0.98	25.00
1	1.00	25.40